



# ALPHA

engineered composites

145 Lehigh Avenue, Lakewood, NJ 08701  
**T:** 732.634.5700 **F:** 732.634.1430 [alphainc.com](http://alphainc.com)

<b>VR 10</b>				
<b>DESCRIPTION</b>	Reinforced Bleached Kraft-Metallized Polypropylene Film Laminate			
<b>APPLICATIONS</b>	Metal Building Insulation Facing			
<b>CERTIFICATIONS</b>	Meets all criteria for ASTM C1136 Types I, II, III, IV UL 723/ASTM E84, ULC-S102M fire testing			
<b>COMPOSITION</b>				
<b>COMPONENT</b>	<b>DESCRIPTION</b>	<b>VALUES*</b>		
		<b>English</b>	<b>Metric</b>	
White Film	Metallized Polypropylene	0.0011 inch	28.0 micron	
Adhesive	Flame Resistant			
Reinforcement	Tri-directional Fiberglass	5/inch (MD) 5/inch (CD)	20/100 mm (MD) 20/100 mm (MD)	
Kraft	White	12 lb./3000 SF	20 g/SM	
<b>TYPICAL PHYSICAL PROPERTIES</b>				
<b>CHARACTERISTIC</b>	<b>METHOD</b>	<b>VALUES*</b>		
		<b>ENGLISH</b>	<b>METRIC</b>	
BASIS WEIGHT	Scale	18.5 lbs/1000 SF	82.5 g/SM	
THICKNESS	ASTM-D-1777	0.009"	229 microns	
PERMEABILITY (WVTR)	ASTM-E-96	0.02 Perms	1.15 ng/N's	
BURST STRENGTH	ASTM-D-774	100 psi	7.3 kg/cm <sup>2</sup>	
TENSILE STRENGTH	ASTM-C-1136	50 lbs/inch MD 45 lbs/inch CD	8.75 kN/m 6.13 kN/m	
ACCELERATED AGING	30 days @ 95% RH, 120 °F (49°C)	No Corrosion No Delamination	No Corrosion No Delamination	
TEMPERATURE RESISTANCE		-40 °F to 220 °F	-40 °C to 104 °C	
WATER IMMERSION	24 hours @ 73°F (23°C)	No Delamination	No Delamination	
MOLD RESISTANCE	ASTM-C-665	No Growth	No Growth	
LIGHT REFLECTIVITY	ASTM C523	85%	85%	
Physical properties are based upon nominal values. Weight / Thickness +/- 10%				
<b>FIRE TESTING</b>		<b>UL723/ASTM E84</b>		
		<u>Composite</u>	<u>Film</u>	<u>Kraft</u>
	FLAME SPREAD	25	5	0
	SMOKE DEVELOPED	50	20	15

**DATA SHEET 14045 REV. E DATE: 10/07/13 \*All values are nominal unless otherwise specified.**

Note: Alpha's metal building insulation facings are produced with plastic films containing ultraviolet (UV) inhibitors, however, intense exposure to UV sources such as direct or indirect sunlight and/or high-output UV lighting is not recommended as these will degrade the plastic film facing.